

MARK-3[®]

SERIES


Decals

Overview:











Along with the introduction of the new 50:1 fuel mix ratio, several MARK-3 decals have recently been updated. The following tech-note lists the available decals related to the MARK-3.

Updated decals:

The figures below indicate the locations and item numbers of the recent MARK-3 decals. *Note: serial number decals not shown.*



The table below lists the most up-to-date MARK-3 decals. *Note: images are not to scale.*

<p>A-4030 DECAL MARK-3 CARBURETOR SHROUD (700962)</p> <div style="border: 1px solid black; padding: 10px;"> <p style="text-align: center;">MARK-3®</p> <hr/> <p>FUEL & LUBRICATION FUEL MIX RATIO: 50:1. GAS: UNLEADED 87 OCTANE, MAX 10% ETHANOL. OIL: 2-CYCLE MIXING OIL WITH API-TC, JASO FD, ISO-L-EGD CERTIFICATION.</p> <p>OPERATING INSTRUCTIONS</p> <ol style="list-style-type: none"> 1. FILL FUEL TANK WITH PROPER FUEL MIXTURE. 2. CONNECT FUEL SUPPLY LINE TO ENGINE. 3. PUMP FUEL TO FILL SUPPLY LINE UP TO CARBURETOR. 4. CONNECT SUCTION AND DISCHARGE HOSE TO PUMP. 5. PRIME PUMP END. 6. POWER UP DOS: CRANK OVER ENGINE 1-2 TIMES, LED WILL BLINK. 7. IF ENGINE IS COLD, ENGAGE THE CHOKE. 8. MOVE THROTTLE TO "START" POSITION. 9. SLOWLY TURN ENGINE UNTIL RESISTANCE (PAST COMPRESSION). 10. GIVE STARTER CORD A QUICK AND STEADY PULL. 11. DISENGAGE CHOKE AND ALLOW ENGINE TO WARM UP FOR A MINIMUM OF 2 MINUTES BEFORE USING FULL THROTTLE. <p>NOTES</p> <ul style="list-style-type: none"> • DO NOT USE NOZZLE LARGER THAN 1/8" (12.7 MM). • CUT-OUT SWITCH MUST NOT BE MADE INOPERATIVE. <p style="text-align: center;">www.waterax.com</p> </div> <div style="display: flex; justify-content: space-between; align-items: center; margin-top: 10px;"> <div style="text-align: center;"> <p>STOP</p>  </div> <div style="text-align: center;"> <p>START</p>  <p>WARM UP</p> </div> </div> <div style="display: flex; justify-content: space-between; align-items: center; margin-top: 10px;"> <div style="text-align: center;"> <p>MAXIMUM</p>  <p>POWER</p> </div> </div>	<p>DECAL MARK-3 WARNING SYMBOLS (701222)</p> <div style="border: 1px solid black; padding: 5px; text-align: center;"> <p>⚠ WARNING</p>  </div> <p>DECAL OIL/FUEL MIX RATIO (701239)</p> <div style="border: 1px solid black; padding: 5px; text-align: center;"> <p>NOTICE</p> <p style="font-size: 2em;">50:1</p> <p>FUEL MIX RATIO</p> </div> <p>CHOKE DECAL (701226)</p> <div style="border: 1px solid black; padding: 5px; text-align: center;">  </div>
<p>DECAL WATERAX LOGO 5.5" GREY/RED ON WHITE (701220)</p>	<p>DECAL-37 MARK-3 EPA EXEMPTION (700961)</p>
<div style="border: 1px solid black; padding: 10px; text-align: center;">  </div>	<div style="border: 1px solid black; padding: 10px; text-align: center;"> <p>EMERGENCY RESCUE EQUIPMENT EXEMPT FROM EMISSION STANDARDS UNDER 40 CFR 1054.660</p> </div>
<p>DECAL-31 DECAL DECOMPRESSION SWITCH (700919)</p> <div style="border: 1px solid black; padding: 10px; text-align: center;"> <p>PUSH/POUSSER/EMPUJAR</p>  </div>	<p>R-419 DECAL ROTATION ARROW (701014)</p> <div style="border: 1px solid black; padding: 10px; text-align: center;">  </div> <p>DECAL FINGER PINCHING (701240)</p> <div style="border: 1px solid black; padding: 10px; text-align: center;">  </div>
<p>DECAL CAUTION PUMP OPERATION (701219)</p> <div style="border: 1px solid black; padding: 10px;"> <p style="text-align: center;">⚠ CAUTION</p> <ul style="list-style-type: none"> - READ AND UNDERSTAND OWNER'S MANUAL. - ALWAYS USE SUCTION STRAINER. - ALWAYS PRIME PUMP BEFORE STARTING ENGINE (EXCEPT EXHAUST PRIMER). - DO NOT RUN PUMP DRY (MAX 30 SEC. WHEN USING EXHAUST PRIMER). - DO NOT CLOSE PUMP DISCHARGE FOR MORE THAN 30 SECONDS. - DO NOT EXCEED MAXIMUM PUMP PRESSURE. - DRAIN PUMP AFTER EACH USE. </div>	<p>DECAL-35 DECAL NO GREASE (700994)</p> <div style="border: 1px solid black; padding: 10px; text-align: center;">  </div>

