

MARK-3[®]

SERIES

FUEL LINE CHECK VALVE

Overview:

WATERAX moved the location of the external check valve on two models of its MARK-3 fuel line to improve priming performance.

Fuel Check Valve:

Due to inconsistencies with the priming bulb's internal check valves, the external fuel check valve on two models of the MARK-3 fuel lines is now located 2.5" after the outlet of the priming bulb. This improves the performance of the priming bulb and ensures that it functions well in all positions, particularly for fuel tanks with a top inlet.

The fuel line models affected are the 12-401B-NS (600390) and 12-401B-NSC (600605). The check valve item number remains 701450.

ID	ITEM NO	DESCRIPTION	QTY
-	600390	12-401B-NS FUEL LINE, STANDARD STYLE	-
1	700017	12-65 COUPLING SWIVEL	1
2	800866	QHOSFS1/4X1B BRAIDED HOSE 1/4"ID X1/2"OD	3.33
3	701450	FUEL CHECK VALVE 1/4" BARB	1
4	800440	12-406N SINGLE EAR OETIKER CLAMP	5
5	600389	12-405-1 FUEL LINE PRIMING BULB	1
6	800864	FA-451 FEM QUICK-CONNECT	1

ID	ITEM NO	DESCRIPTION	QTY
-	600605	12-401B-NSC COMPLETE FUEL LINE,STD STYLE	-
1	700017	12-65 COUPLING SWIVEL	1
2	800814	R-732 CONNECTOR 1/4" TUBE X 1/8" NPT	1
3	700100	A-7487 DUST CAP - FEM CONNECTOR, NITRILE	1
4	800802	R-712 HANDLE QUICK CONNECT, FEM	1
5	701450	FUEL CHECK VALVE 1/4" BARB	1
6	800440	12-406N SINGLE EAR OETIKER CLAMP	5
7	800864	FA-451 FEM QUICK-CONNECT	1
8	600389	12-405-1 FUEL LINE PRIMING BULB	1
9	800866	QHOSFS1/4X1B BRAIDED HOSE 1/4"ID X1/2"OD	3.33

